




REVISION NO.	DATE	BY	DESCRIPTION



KEY






Construction Access Routes (Install Continuous Orange Construction Fencing at Edges of Routes)

Approximate Over-Excavation Boundary

Temporary Chain Link Construction Fence With Locked Entrance



Stabilized Construction Entrance/Exit at Least 50 Feet Long Per California Stormwater BMP Handbook Construction Detail TC-1

NOTES: All locations shown are approximate; actual locations to be determined by the Engineer during construction. All disturbed areas shall be repaired to original grades and stabilized per the General Notes, Erosion Control Notes, and Sediment Control Notes shown on Sheet 10.



SITE ACCESS AND STAGING AREA PLAN

SHEET

2 of 10 Sheets

HILLVIEW DRIVE SLOPE REPAIR

Vista Tassajara, Danville, California